

Inspection Photos
Operator: Winn Exploration
Location/API #: 043-06215
Date: 2-26-2019



Photo 1. View of project area from the southeastern portion facing westward.



Photo 2. View of soil pile within the project area facing northwestward.



Photo 3. Closeup view wattles along the northeastern edge of the project area. These will need to be removed when the location is stabilized and ready to pass reclamation.



Photo 3. View of black netting debris that needs to be removed.



Photo 5. View of the eastern edge of the project area facing southward.