

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/12/2019

Submitted Date:

03/14/2019

Document Number:

689500951

FIELD INSPECTION FORM

Loc ID 336703 Inspector Name: Oakman, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCinspections@anadarko.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
118126	PIT				-	ARISTOCRAT	EI
241891	WELL	SI	05/01/2017	GW	123-09682	ARISTOCRAT 41-9 1	EI
280889	WELL	SI	05/01/2017	GW	123-23318	REI 1-9	EI

General Comment:

[COGCC Environmental Inspection to determine the status of pit facility ID 118126.](#)

[The pit status has been changed to closed. However, the operator is instructed to submit a Form 27 for site characterization of the historic pit area.](#)

Inspected Facilities

Facility ID: 118126 Type: PIT API Number: - Status: Insp. Status: EI

Facility ID: 241891 Type: WELL API Number: 123-09682 Status: SI Insp. Status: EI

Facility ID: 280889 Type: WELL API Number: 123-23318 Status: SI Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: The pit location was determined based on historical documents and aerial imagery. Distressed vegetation is present at the historic pit location.

Corrective Action: Operator shall submit a Form 27 Site Investigation and Remediation Workplan for for thehistoric pit area. Date: 04/12/2019

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
Contact area EPS Nikki Graber with any questions regarding pit status	oakmank	03/14/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689500952	Pit Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4763057