

PIT STATUS EVALUATION FORM

Facility ID: 115073

Pit Name: AMOCO UPRR 23-4

Duplicate Record(s) Pit #



Legend

- Database Pit Location
- Producing Well
- + Shut In Well
- ♂ Temp Aban Well
- ♂ Abandoned Well
- ⊗ Dry & Aban Well
- ◆ Injection Well
- Other Well Status




Image Source:
 USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPANOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: SOHIO PETR CO AKA STANDARD OIL
 T: 6S R: 63W Sec: 23 QQ: NWNW 6th Meridian
 Latitude: 39.518667 Longitude: -104.420323 NAD83

County: Elbert, CO
 County Code: 039

Pit Status Evaluation

- Active** Form 15: Pit Permit _____ Assoc. Well Seq No(s) _____
 Other documentation _____
 Aerial photo verification _____
- Closed** Form 27: Remediation Workplan _____
 Form 4: Sundry Notice _____
 Rule 903a.(2)B
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
 Well API Seq #(s) 06267 PA (2-20-1985)
 Other documentation WSIF# 445074 (1987)
- Abandoned** Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 Unknown No Site Visit
 Add'l Review

Notes: WSIF pit backfilled & site clean