

**Inspection Photos**  
**Location Name: JOHNSON-66N66W /11SESE**  
**Location #: 329817**



**Photo #1**  
**Johnson 11-16G6 (05-123-17881) Wellsite**  
**Plugged & Abandoned | PA**  
**NOT Cut & Capped – Casing & Valve appears in place**



**Photo #2**  
**Johnson 11-16G6 Abandoned Battery site**  
**Unused Equipment**  
**Gas meter run, Gas line riser, Signs**

