

Final Reclamation and Stormwater Inspection

March 1, 2019

Operator: PDC ENERGY INC # 69175

Location ID: 331679

Inspection Document #: 674902640

Weld County, CO

NENW Section 28 T2N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PDC ENERGY INC/2N64W28
Location ID: 331679



Photo 1. Photo taken from the location, facing Northeast. Appears the Operator has performed final reclamation activities with drill seed rows and straw crimped mulch.



Photo 2. Photo taken from the location. Photo depicts the current reclamation status.

Inspection Photos

Location Name: PDC ENERGY INC/2N64W28

Location ID: 331679



Photo 3. Photo taken from the location, facing Northwest. See comments from Photo 1.



Photo 4. Photo taken from the location, facing West. See comments from Photo 1.

Inspection Photos
Location Name: PDC ENERGY INC/2N64W28
Location ID: 331679



Photo 5. Photo taken from the location, facing Southwest. Photo depicts apparent erosion observed on location.



Photo 6. Photo taken from the location, facing North. See comments from Photo 5.