

Final Reclamation and Stormwater Inspection

March 1, 2019

Operator: PDC ENERGY INC # 69175

Location ID: 305082

Inspection Document #: 674902641

Weld County, CO

SWNE Section 28 T2N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PDC ENERGY INC/2N64W28
Location ID: 305082



Photo 1. Photo taken from the access road off CR 18, facing South. Photo depicts the access road is still in tact with gravel remaining along the northern portion.



Photo 2. Photo taken from the access road off CR 18, facing South. Photo depicts the access road is still in tact and the culvert remains on location.

Inspection Photos

Location Name: PDC ENERGY INC/2N64W28

Location ID: 305082



Photo 3. Photo taken from the facility location, facing South. Appears Operator has recently performed reclamation activities with drill rows observed but no straw crimped mulch.



Photo 4. Photo taken from the location, facing Southwest. See comments from Photo 3.

Inspection Photos
Location Name: PDC ENERGY INC/2N64W28
Location ID: 305082



Photo 5. Photo taken from the location, facing West. Appears Operator has recently performed reclamation activities at the location and access road with drill rows observed but no straw crimped mulch. No stormwater BMPs observed at location.



Photo 6. Photo taken from north of the access road, facing Southwest. See comments from Photo 5.