

# Final Reclamation and Stormwater Inspection

March 1, 2019

Operator: PDC ENERGY INC # 69175

Location ID: 305083

Inspection Document #: 674902642

Weld County, CO

SENE Section 28 T2N R64W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: PDC ENERGY INC/2N64W28

Location ID: 305083



**Photo 1.** Photo taken from the access road looking into the location, facing West. Appears Operator has recently performed reclamation activities at the location with drill rows observed but no straw crimped mulch.



**Photo 2.** Photo taken from the access road, facing East. Appears that the access road was reclaimed sometime in the past.

Inspection Photos

Location Name: PDC ENERGY INC/2N64W28

Location ID: 305083



**Photo 3.** Photo taken from the location, facing Northwest. See comments from Photo 1.



**Photo 4.** Photo taken from the location, facing Southeast. See comments from Photo 1.