

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2019

Submitted Date:

03/08/2019

Document Number:

696100421

FIELD INSPECTION FORM

Loc ID: 306003 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 10 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 100322
 Name of Operator: NOBLE ENERGY INC
 Address: 1001 NOBLE ENERGY WAY
 City: HOUSTON State: TX Zip: 77070

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284464	WELL	SI	06/01/2018	OW	123-23814	TJADEN 36-11	TA

General Comment:

This is a WELL & ABANDONED BATTERY Inspection.
 Well is TA.
 Battery is Abandoned & ALL equipment except gas meter run & signs has been removed.
 Abandoned Battery SE corner GPS coordinates: 40.536093, -104.832580
 Follow-up to FIR #691300373 dated 07/12/2018.
 1 of 1 Corrective Actions from previous FIR has been addressed.
 1.) LTSI well had no MIT on record.
 No orange decommission tag present per SI/TA well per variance Doc #401474555. (NOBLE).
 Orange tag is now posted. See photos #1-2.
 2.) Unused equipment noted at wellsite. Unused equipment at wellsite has been removed. See photos #1-2.

1-Corrective Action identified on this FIR.
 1.) Unused gas meter run & signs at Abandoned Battery site.
 Refer to Rule 603.f for guidance when machinery required to remove equipment (90 Days). See photo #3.
 Remove unused gas meter run & signs at Battery site. Comply w/ Rule 603.f.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	LTSI well had no MIT on record. From prior FIR: No orange decommission tag present per SI/TA well per variance Doc #401474555. (NOBLE). Orange tag is now posted. See photos #1-2.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		Date: _____
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment noted at wellsite from prior FIR. Unused equipment at wellsite has been removed. See photos #1-2.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter run & signs at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment (90 Days). See photo #3. Remove unused gas meter run & signs at Battery site. Comply w/ Rule 603.f.		
Corrective Action:	Remove unused gas meter run & signs at Battery site. Comply w/ Rule 603.f.		Date: 06/06/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Equipment:			
Type: Other	# 1		corrective date
Comment:	Wellhead w/ master valve, casing head & valves.		
Corrective Action:		Date:	

Type: Other	# 1	
Comment:	Bradenhead appears plumbed to surface.	
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 284464 Type: WELL API Number: 123-23814 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Observed well TA & LOTO. Battery has been abandoned with all production equipment removed.
SI/TA well per variance Doc #401474555. (NOBLE).
Orange decommission tag is posted.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401965981	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4756654
696100422	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4756640