

## Inspection Photos

Location Name: LOWELL BRADY 23-3A

Location ID: 05-103-07642

Inspection: 679703382



**Photo 1. Location looking east.**



**Photo 2. No berm on east side of tank battery.**

