

**SG 13-26**  
**Api# 05-045-15374**  
**Inspection # 689702857**



**Fence around well heads is down.**

SG 13-26  
Api# 05-045-15374  
Inspection # 689702857



Volumes are faded and faint on labels. No secondary containment for tank.

**SG 13-26**  
**Api# 05-045-15374**  
**Inspection # 689702857**



**Volumes are faded and faint on labels.**