

Inspection Photos

Location Name: HSR-KNOX-65N67W /3NWSE

Location #: 332954



Photo #1

Shur View 23-3 (05-123-24195) Wellsite

Plugged & Abandoned | PA

≈ 125 yds.



Photo #1

Shur View 23-3 Abandoned Battery site

**Unused Equipment
Latrine, Pig Launcher**