

Inspection Photos

Loc#436004

Operator: Ursa

Inspection Number: 692400776

Inspection Date: 3/15/19





Photo#1:

Overview of Location from entry to North.

March 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Valley Farms O Pad Loc#436004



Photo#2:
Ditch needs some general maintenance.

March 15, 2019



Photo#3:
BMP needs to be installed along along inside base of berm.



Photo#4:
Stormwater outlet and BMPs at Northeast corner of site are not installed or designed according to good engineering practices

March 15, 2019




Photo#5:
Stormwater outlet and BMPs at Northeast corner of site are not installed or designed according to good engineering practices



Photo#6:
There is evidence of Annual Weed Growth that becomes Debris.

March 15, 2019



Photo#7:
There is evidence of Annual Weed Growth that becomes Debris .



Photo#8:
Berm needs to be stabilized.

March 15, 2019



Photo#9:
Berm needs to be stabilized.