

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/15/2019

Submitted Date:

03/15/2019

Document Number:

692601547**FIELD INSPECTION FORM**Loc ID 337664 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287632	WELL	PR	05/01/2007	GW	125-10460	NEWTON 11-4	PR

General Comment:Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 0		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas scrubber (not in use)		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	287632	Type:	WELL	API Number:	125-10460	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Pump unit removed and downhole equipment still in wellbore at time of inspection. Central meter run for (Newton 4-5-1, Newton 22-4, 11-4, 31-5, Newton 5-1-2) 1160' SW of wellhead @ Newton 4-5-1								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT