

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/18/2019

Submitted Date:

03/18/2019

Document Number:

679600487**FIELD INSPECTION FORM**
 Loc ID 327047 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246263	WELL	SI	01/01/2017	GW	123-14060	VETTING PM F 26-2	AL

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter house west side of location. See attached photo#3		
Corrective Action:	Comply with Rule 603.f	Date:	06/18/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 246263 Type: WELL API Number: 123-14060 Status: SI Insp. Status: AL

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday, March 18, 2019 at approximately 11:26, I, Inspector Brittani Santistevan, conducted an on-site inspection at Vetting PM F 26-2 (Noble Energy), at location #: 327047 in Weld County, Colorado.</p> <p>While there, I observed an abandoned location and puddles of water on access road to where wellhead was previously located.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1: Unused equipment (gas meter house) Comply with Rule 603.f .</p> <p>See attached photo #3.</p> <p>Form 6 (DOC# 401893298) is in data base.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	03/18/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679600488	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766218