

Inspection Photos
Location Name: Cosslett #2
Location ID: 317983



Photo 1 PU and WH



Photo 2 stained soil and mechanical WH packing appears to be leaking.

Inspection Photos
Location Name: Cosslett #2
Location ID: 317983



Photo 3 Anadarko building location next to well site



Photo 4 Anadarko building location next to well sitw