

Inspection Photos
Location Name: Cosslett #1
Location ID:317708



Photo 1 WH and PU



Photo 2 TNK BTRY. BTRY sign does not reflect wells associated with battery

Inspection Photos
Location Name: Cosslett #1
Location ID:317708



Photo 3 Meter house. Riser is bull plugged and marked



Photo 4 sales line from meter house is LOTO by Anadarko

Inspection Photos
Location Name: Cosslett #1
Location ID:317708



Photo 5 Separator appears to have approximately 90psi



Photo 6 ECD, separator and compressor