

PIT STATUS EVALUATION FORM

Facility ID: 115127

Pit Name: MAPLE UPRR 3X

Duplicate Record(s) Pit #



Legend

- Database Pit Location
- Producing Well
- + Shut In Well
- ⊕ Temp Aban Well
- ⊗ Abandoned Well
- ⊙ Dry & Aban Well
- ◆ Injection Well
- Other Well Status

1:6,000

0 250 500 750 Feet

Image Source:
 USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPOULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: ROCK OIL CORP
 T: 7S R: 63W Sec: 10 QQ: NENE 6th Meridian
 Latitude: 39.460708 Longitude: -104.424753 NAD83

County: Elbert, CO
 County Code: 039

Pit Status Evaluation

Active Form 15: Pit Permit N/A Assoc. Well Seq No(s) _____
 Other documentation _____
 Aerial photo verification _____

Closed Form 27: Remediation Workplan _____
 Form 4: Sundry Notice _____
 Rule 903a.(2)B _____
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
 Well API Seq #(s) PA#06500 (8-19-1985)
 Other documentation WSIF# 453154 (4-16-1987)

Abandoned Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 Unknown No Site Visit
 Add'l Review

Notes: No Form 15. WSIF (1987) pit backfilled & site clean.