

Inspection Photos

3/18/2019

Operator: MALLARD EXPLORATION LLC - 10670

Location ID: 447902

Inspection Doc. Number: 682504599

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the east end of the pad, facing south. Photo shows operator appears to have installed an additional berm on the southeastern corner of the pad.



Photo 2: Photo taken from the south end of the pad, facing south. Photo shows section of stormwater ditch where discharge was occurring has been repaired to mitigate runoff.