

Inspection Photos
Location Name: COLORADO GRAND 12-26
API #: 05-071-07590
Insp. Doc. # 695100364



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: COLORADO GRAND 12-26
API #: 05-071-07590
Insp. Doc. # 695100364



PHOTO 3: IMPACTED SOIL AROUND WELLHEAD



**PHOTO 4: IMPACTED SOIL NEAR SEPARATOR DRAIN ON
METER HOUSE**