

PIT STATUS EVALUATION FORM

Facility ID: 115136

Pit Name: AMOCO 13-16

☒ Duplicate Record(s) Pit #
115064



Legend

- ☒ Database Pit Location
- ☒ Producing Well
- ☒ Shut In Well
- ☒ Temp Aban Well
- ☒ Abandoned Well
- ☒ Dry & Aban Well
- ☒ Injection Well
- ☒ Other Well Status



1:6,000
0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery
Program (NAIP), 2006

ΣΠ S.S. PAPADOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: MAZUMA TURNKEY CONTRACTORS INC
T: 6S R: 64W Sec: 13 QQ: SESE 6th Meridian
Latitude: 39.522207 Longitude: -104.497636 NAD83

County: Elbert, CO
County Code: 039

Pit Status Evaluation

- ☐ Active ☐ Form 15: Pit Permit NA Assoc. Well Seq No(s) _____
☐ Other documentation _____
☐ Aerial photo verification _____
- ☐ Closed ☐ Form 27: Remediation Workplan _____
☐ Form 4: Sundry Notice _____
☐ Rule 903a.(2)B _____
☒ Evidence pit(s) existed, no closure docs & well not PR, AC or SI
Well API Seq #(s) 06370 PA (11-16-1981)
☒ Other documentation WSIF #44/263 (11-1-1988)
- ☐ Abandoned ☐ Possible un-reclaimed pit(s) or adverse conditions, no closure docs ☐ Site Visit
☐ No Site Visit
☐ Add'l Review
- ☐ Unknown

Notes: WSIF (1988) "pits backfilled & site clean"
DUPLICATE RECORD Pit status & documentation
under Facility ID # 115064