


PIT STATUS EVALUATION FORM

Facility ID: 115145
 Pit Name: LAUREL 1

Duplicate Record(s) Pit #



Legend

- Database Pit Location
- Producing Well
- + Shut In Well
- ⊕ Temp Aban Well
- ⊗ Abandoned Well
- ⊘ Dry & Aban Well
- ◆ Injection Well
- Other Well Status



Image Source:
 USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: ROCK OIL CORP
 T: 6S R: 63W Sec: 23 QQ: NWSE 6th Meridian
 Latitude: 39.511407 Longitude: -104.410953 NAD83

County: Elbert, CO
 County Code: 039

Pit Status Evaluation

- Active** Form 15: Pit Permit N/A Assoc. Well Seq No(s) _____
 Other documentation _____
 Aerial photo verification _____
- Closed** Form 27: Remediation Workplan _____
 Form 4: Sundry Notice _____
 Rule 903a.(2)B _____
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
 Well API Seq # (s) 06454 PA (5-18-1990)
 Other documentation WSIF # 445073 (7-19-1990)
- Abandoned** Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 Unknown No Site Visit
 Add'l Review

Notes: No Form 15, WSIF (1990) pits backfilled & site clean