

# Final Reclamation Inspection

March 15, 2019

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 424579

Inspection Document #: 682404670

Weld County, CO

NWNW Section 8 T7N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Pergamos /8-11-7-60  
Location ID: 424579



**Photo 1.** Photo taken from the entrance of the location on January 28, 2019, facing East. Photo taken from the locked gate entrance to the location. Operator constructed the location but never drilled the proposed well. Operator has instead turned the location into a storage yard. Spills were observed throughout the location outside of containment, as well as unmanaged weeds. Operator shall clean up all spills, control/remove weeds, remove all equipment, and perform Final Reclamation.

**Photo 2.** Photo taken from the entrance of the location on March 15, 2019, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: Pergamos /8-11-7-60  
Location ID: 424579



**Photo 3.** Photo taken from the northwestern location on January 28, 2019, facing West. See comments under Photo 1.



**Photo 4.** Photo taken from the northwestern location on March 15, 2019, facing West. Operator has failed to remove trash, debris, storage of supplies and unused equipment.

Inspection Photos  
Location Name: Pergamos /8-11-7-60  
Location ID: 424579



**Photo 5.** Photo taken from the northwestern location on January 28, 2019, facing Southwest. See comments under Photo 1.



**Photo 6.** Photo taken from the northwestern location on March 15, 2019, facing Southwest. See comments under Photo 4.

Inspection Photos  
Location Name: Pergamos /8-11-7-60  
Location ID: 424579



**Photo 7.** Photo taken from the western location on January 28, 2019, facing South. See comments under Photo 1.



**Photo 8.** Photo taken from the western location on March 15, 2019, facing South. See comments under Photo 4.

Inspection Photos  
Location Name: Pergamos /8-11-7-60  
Location ID: 424579



**Photo 9.** Photo taken from the southern location on March 15, 2019, facing Northwest. Barrels have not been put in containment. Note: Snow cover did not allow COGCC staff to make an accurate assessment to determine whether or not all spills were cleaned up.



**Photo 10.** Photo taken from the northeast location on March 15, 2019, facing North. See comments under Photo 4.