

Inspection Photos
Location Name: CARPIO-66N64W /22SWSE
Location #: 332240



Photo #1
Carpio 22-43 (05-123-22024) Wellsite
Temporarily Abandoned | TA
Weeds
from prior FIR



Photo #2
Carpio 22-43 Wellsite
Plugged & Abandoned | PA
Wellhead NOT cut & capped
Unused Equipment

Inspection Photos

Location Name: CARPIO-66N64W /22SWSE

Location #: 332240



Colorado Oil & Gas Conservation Commission

40.46819, -104.53576, 1427.0m, 179°

2018/10/25 11:22:58 AM

Photo #4

Carpio 22-43 Battery

from prior FIR



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources