

Inspection Photos

Location Name: SUGHROUE-66N64W /33NENE

Location #: 327172



Colorado Oil & Gas Conservation Commission
40.44846, -104.54765, 1418.0m, 176°
2019/03/20 04:25:48 PM

Photo #1

Sughrue 41-33 (05-123-14261) Wellsite

Shut-In | SI - LOTO



Colorado Oil & Gas Conservation Commission
40.44971, -104.5477, 1397.0m, 128°
2019/03/20 04:30:47 PM

Photo #2

Sughrue 41-33 Battery

Shut-down



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources