

Final Reclamation and Stormwater Inspection

March 12, 2019

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 318435

Inspection Document #: 674902661

Weld County, CO

SWNW Section 3 T1N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KP KAUFFMAN COMPANY INC /1N68W3

Location ID: 318435



Photo 1. Photo taken from the access road off, facing North. Photo depicts the access road remains on location, the gravel has not been removed and has not been re-contoured or re-graded and decompacted to meet the adjacent terrain.



Photo 2. Photo taken from the location. See comments from Photo 1.

Inspection Photos

Location Name: KP KAUFFMAN COMPANY INC /1N68W3

Location ID: 318435



Photo 3. Photo taken from the location, facing North. Photo depicts equipment left on site.



Photo 4. Photo taken from the location, facing North. See comments from Photo 3.

Inspection Photos

Location Name: KP KAUFFMAN COMPANY INC /1N68W3

Location ID: 318435



Photo 5. Photo taken from the location, facing North. Photo depicts the presence of undesirable species and other weeds including but not limited to kochia. The reclamation is not at percent cover and has non-uniform establishment of perennial cover.



Photo 6. Photo taken from the location, facing West. See comments from Photo 5.