

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/21/2019

Submitted Date:

03/21/2019

Document Number:

692601576

FIELD INSPECTION FORM

Loc ID 314215 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 383 INVERNESS PKWY, STE 360
City: ENGLEWOOD State: CO Zip: 80112

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Strachan, Steve	(303) 785-7006	sms@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275439	WELL	PR	06/01/2017	GW	099-06881	GRUENLOH 2	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Dirt road through CRP		
Corrective Action		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:				corrective date
Type: Gas Meter Run	# 1			
Comment:	Meter shed is on south side of water tank			
Corrective Action:		Date:		
Type: Horizontal Heated Separator	# 1			
Comment:	HHS next to meter shed			
Corrective Action:		Date:		

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		37.972830,-102.501020
Comment:	Fiberglass open top water tank on west side of production tank				
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shared berms						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	FIBERGLASS AST		37.972830,-102.501020	
Comment:						
Corrective Action:				Date:		
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Berms need maintenance						
Corrective Action:				Date:		
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:				Date:		

Inspected Facilities

Facility ID: 275439 Type: WELL API Number: 099-06881 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT