

Inspection Photos
Location Name: FEDERAL 1-30
Location ID: 05-103-08096
Inspection: 679703426



03/22/2019

Photo 1. Location looking northwest.



03/22/2019

Photo 2. Pump jack.



Inspection Photos
Location Name: FEDERAL 1-30
Location ID: 05-103-08096
Inspection: 679703426



Photo 3. Water tank



Photo 4. Water tank with holes at base.

Inspection Photos
Location Name: FEDERAL 1-30
Location ID: 05-103-08096
Inspection: 679703426



Photo 5. Crude tank, gas building, vertical separator.



Photo 6. Horizontal separator.

Inspection Photos
Location Name: FEDERAL 1-30
Location ID: 05-103-08096
Inspection: 679703426



Photo 7. Container without contents label & secondary containment.



Photo 8. Barrel without label & secondary containment.

Inspection Photos
Location Name: FEDERAL 1-30
Location ID: 05-103-08096
Inspection: 679703426



Photo 9. Vessel without contents label.



Photo 10. Horizontal separator stack without visible bird protection.