

Inspection Photos

Location Name: NOFFSINGER-66N64W /33SENW

Location #: 331154



Photo #1

Noffsinger 22-33 (05-123-20237) Wellsite

Shut-In | SI

*Weeds need mitigated
from prior FIR*



Photo #2

Noffsinger 22-33 Wellsite

Shut-In | SI

Weeds appear mitigated



Inspection Photos

Location Name: NOFFSINGER-66N64W /33SEnw

Location #: 331154



Photo #3

Noffsinger 12-33, 22-33, 32-33 Battery

Shut-down

from prior FIR

