

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: UNUSED EQUIPMENT

Comment: Unused gas meter house west side of location. See attached photo#3

Corrective Action: Comply with Rule 603.f

Date: 06/18/2019

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Gas Meter Run

1

corrective date

Comment:

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 246263 Type: WELL API Number: 123-14060 Status: SI Insp. Status: AL**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday, March 18, 2019 at approximately 11:26, I, Inspector Brittani Santistevan, conducted an on-site inspection at Vetting PM F 26-2 (Noble Energy), at location #: 327047 in Weld County, Colorado. While there, I observed an abandoned location and puddles of water on access road to where wellhead was previously located. During this inspection the following possible compliance issues were observed: 1: Unused equipment (gas meter house) Comply with Rule 603.f . See attached photo #3.</p> <p>Form 6 (DOC# 401893298) is in data base. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	03/18/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401976676	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766222
679600488	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766218