

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401983150

Date Received:

03/25/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 679702802

Inspection Date: 01/29/2019

FIR Submit Date: 01/29/2019

FIR Status:

Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 441601

Location Name: RNPU Number: 197-15A2H County: RIO BLANCO

Qtrqtr: NWSE Sec: 15 Twp: 1S Range: 97W Meridian: 6

Latitude: 39.962900 Longitude: -108.266652

FACILITY - API Number: 05-103-00 Facility ID: 441602

Facility Name: RNPU Number: 197-15A1

Qtrqtr: NWSE Sec: 15 Twp: 1S Range: 97W Meridian: 6

Latitude: 39.962900 Longitude: -108.266652

CORRECTIVE ACTIONS:

1 CA# 122123

Corrective Action: Comply with Rule 603.f .
Removal of surplus equipment not needed for drilling of the new well.

Date: 04/30/2019

Response: CA COMPLETED

Date of Completion: 03/21/2019

Operator Comment: Removal of surplus equipment not needed for drilling of the well has been completed, see attached photos.

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: Removal of surplus equipment not needed for drilling of the well has been completed, see attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Dooling

Signed: _____

Title: Regulatory Coordinator

Date: 3/25/2019 9:21:53 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401983162	Photos of completed CA-surplus equipment removed
-----------	--

Total Attach: 1 Files