

Inspection Photos
Location Name: Dacono #2
Location ID:311311



Photo 1 Dacono #2 WH



Photo 2 Dacono #1 WH

Inspection Photos
Location Name: Dacono #2
Location ID:311311



Photo 3 Dacono #3 WH



**Photo 4 TNK BTRY battery location is next to Colorado BLVD
needs to be painted appropriate color**

Inspection Photos
Location Name: Dacono #2
Location ID:311311



Photo 5 loc pic



Photo 6 loc pic

Inspection Photos
Location Name: Dacono #2
Location ID:311311



Photo 7 Trash Debris(weeds) and unused equipment



Photo 8 loc pic Depris (weeds) Unused equipment

Inspection Photos
Location Name: Dacono #2
Location ID:311311



Photo 9 Trash, Debris(weeds) and unused equipment pip rack and ECD



Photo 10 Unused equipment and improper storage of fluids

Inspection Photos
Location Name: Dacono #2
Location ID:311311



Photo 11 Trash, Debris(weeds) and unused equipment pipe rack, poly pipe and separators



Photo 12 Trash, Deris(weeds) Unused equipment and improper storage of fluids

Inspection Photos
Location Name: Dacono #2
Location ID:311311



Photo 13 Trash, Debris(weeds) wood and unknown trash



Photo 14 Trash, Deris(weeds) Unused equipment and improper storage of fluids

Inspection Photos
Location Name: Dacono #2
Location ID:311311



**Photo 15 Trash, Debris(weeds) pellets and unknown trash,
Improper storage of fluids**



Photo 16 Separator and ECD

Inspection Photos
Location Name: Dacono #2
Location ID:311311




Photo 17 Stained soil inside pump house



Photo 18 Stained soil inside pump house

Inspection Photos
Location Name: Dacono #2
Location ID:311311



Photo 19 improper storage of fluids containers not marked with identifying fluid.



Photo 20 Trash, Debris (weeds) unused equipment PU weight, Pipe and separators