

Inspection Photos
Location Name: Miller 1-17
Location ID: 328938



Photo 1 WH. Appears to be a leak on ¼ gas line to drip pot