

Inspection Photos
Location Name: Miller #43-17
Location ID:305786



Photo 1 Well is P&A unused equipment (PU horses head)

Photo 2 electric power has been removed