

Inspection Photos
Location Name: PHILADELPHIA CREEK 22
Location ID: 05-103-08363
Inspection: 679703457



Photo 1. Location looking southwest.



Photo 2. Tank without label.

Inspection Photos

Location Name: PHILADELPHIA CREEK 22

Location ID: 05-103-08363

Inspection: 679703457



Photo 3. Unused white container next wellhead.



Photo 4. Unused valves next to separator.

