

PIT STATUS EVALUATION FORM

Facility ID: 115183

Pit Name: CHAMPLIN 569 "E" 2

☐ Duplicate Record(s) Pit #

115182 through 115187



Legend

- ☐ Database Pit Location
- ☐ Producing Well
- ☐ Shut In Well
- ☐ Temp Aban Well
- ☐ Abandoned Well
- ☐ Dry & Aban Well
- ☐ Injection Well
- ☐ Other Well Status



1:6,000
0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery
Program (NAIP), 2006

 S.S. PAPADOPOULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: RENEGADE OIL & GAS COMPANY LLC
T: 6S R: 62W Sec: 7 QQ: SENW 6th Meridian
Latitude: 39.543957 Longitude: -104.378062 NAD83

County: Elbert, CO
County Code: 039

Pit Status Evaluation

☐ Active

☐ Form 15: Pit Permit NA Assoc. Well Seq No(s) 06372 (2-3-2004) PR
☐ Other documentation _____
☐ Aerial photo verification _____

☒ Closed

☐ Form 27: Remediation Workplan _____
☐ Form 4: Sundry Notice _____
☐ Rule 903a.(2)B _____
☐ Evidence pit(s) existed, no closure docs & well not PR, AC or SI
Well API Seq #(s) _____
☐ Other documentation FIR# 436674 (5-6-1996)

☐ Abandoned

☐ Possible un-reclaimed pit(s) or adverse conditions, no closure docs

☐ Site Visit
☐ No Site Visit
☐ Add'l Review

☐ Unknown

Notes: Common use battery tank site for Champlin 569 E 1, 2, 3, 4, 5, 6
FIR (1996) "buried concrete vault". API Seq Nos 06354 (PR) 06372 (PR)
06373 (PA) 06374 (PR) 06403 (PR) 06404 (PA)