

Inspection Photos
Location Name: [GEORGE H. GERHARDT #1](#)
Location ID: 336278



Pic 1



Pic 2


Inspection Photos

Location Name: [GEORGE H. GERHARDT #1](#)

Location ID: 336278



Pic 3 possible leak



Pic 4 no wellhead sign on well.

Inspection Photos
Location Name: [GEORGE H. GERHARDT #1](#)
Location ID: 336278



Pic 5



Pic 6

Inspection Photos

Location Name: [GEORGE H. GERHARDT #1](#)

Location ID: 336278



Pic 7 Unused unmarked riser by oil tank



Pic 8 manifold with stained soil.

Inspection Photos

Location Name: [GEORGE H. GERHARDT #1](#)

Location ID: 336278



Pic 9



Pic 10