

Inspection Photos
Location Name: FEDERAL 18-15
Location ID: 05-103-08991
Inspection: 679703494



Photo 1. Location looking south.



Photo 2. Pump jack & separator.

Inspection: 679703494



Photo 3. Methanol tank label.




Photo 4. Tank label with incorrect operator & phone number.

Inspection Photos

Location Name: FEDERAL 18-15

Location ID: 05-103-08991

Inspection: 679703494



Photo 5. Well head sign with incorrect phone number.



Photo 6. Unused pipe.