

Location Name: Markus Production, Inc. – Jolly No. 41 x 6  
Inspection Date: 3/22/2019




Photo # - 1

Location Name: Markus Production, Inc. – Jolly No. 41 x 6  
Inspection Date: 3/22/2019



Photo # - 2

Former tank battery, view west



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Markus Production, Inc. – Jolly No. 41 x 6  
Inspection Date: 3/22/2019



Photo # - 3

Former tank battery, view southwest from former separator area



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Markus Production, Inc. – Jolly No. 41 x 6  
Inspection Date: 3/22/2019



Photo # - 4

Production pit Facility ID 107649 view east



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Markus Production, Inc. – Jolly No. 41 x 6  
Inspection Date: 3/22/2019



Photo # - 5

Production pit Facility ID 107649 view east



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Markus Production, Inc. – Jolly No. 41 x 6  
Inspection Date: 3/22/2019



Photo # - 6

Production pit Facility ID 119049 view north



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources