

Inspection Photos
Location Name: VPR C 115
API #: 05-071-07795
Insp. Doc. # 695100383



PHOTO 1: LOCATION/WELL SIGN



PHOTO 2: WELLHEAD



Inspection Photos
Location Name: VPR C 115
API #: 05-071-07795
Insp. Doc. # 695100383



**PHOTO 3: WELLHEAD IS COATED WITH A GREASY/ OILY
APPEARING SUBSTANCE THAT IS IMPACTING SOIL IN ABOUT A 2'
RADIUS AROUND WELLHEAD.**

