

# Final Reclamation and Stormwater Inspection

March 19, 2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 328587

Inspection Document #: 674902681

Weld County, CO

NWSW Section 24 T3N R64W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: NOBLE ENERGY INC /3N64W24  
Location ID: 328587



**Photo 1.** Photo taken from the access road, facing West. Appears Operator has performed final reclamation activities along the access road and location with native perennial grass establishment in some areas.



**Photo 2.** Photo taken from the access road, facing East. Photo depicts the removal of all equipment has been performed. However it appears the well location is not reflective of the adjacent reference crop areas.

Inspection Photos  
Location Name: NOBLE ENERGY INC /3N64W24  
Location ID: 328587



**Photo 3.** Photo taken from the location, facing East. Photo depicts the removal of all equipment has been performed. However the reclamation is not at percent cover and has non-uniform establishment of perennial cover. The Photo depicts the presence of undesirable species including but not limited to cheatgrass.



**Photo 4.** Photo taken from the location, facing South. See comments from Photo 3.