

Inspection Photos
Location Name: Frank #5
Location ID: 332804



Colorado Oil & Gas Conservation Commission
40.27471, -104.80767, 1434.0m, 228°
04/01/2019 12:09:44 PM

Production facility



Colorado Oil & Gas Conservation Commission
40.27431, -104.80781, 1429.0m, 166°
04/01/2019 12:10:44 PM

Wellhead

Inspection Photos
Location Name: Frank #5
Location ID: 332804



Trash



Lease road

Inspection Photos
Location Name: Frank #5
Location ID: 332804



Lease road



Lease road