

Location Name: Bears 5-30

API: 05-123-34214

Inspection Date: 4/1/2019



Photo of Bears 5-30 casing. Top of photo is east. Fluid flow is from area in red circle on west side.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources