

Inspection Photos
Location Name: Nels Christiansen 1
Location ID: 311282



Pic 1



Pic 2

Inspection Photos
Location Name: Nels Christiansen 1
Location ID: 311282



Pic 3



Pic 4 unused unmarked riser open ended.

Inspection Photos
Location Name: Nels Christiansen 1
Location ID: 311282



Pic 5 Risers not LOTO & pump



Pic 6

Inspection Photos Location Name: Nels Christiansen 1 Location ID: 311282



Pic 7 Gas meter run has not been calibrated since 2007



Pic 8

COLORADO OIL AND GAS CONSERVATION COMMISSION
 40.14194, -104.79639, 4841.2ft, 29°
 04/01/2019 14:19:59

Inspection Photos
Location Name: Nels Christiansen 1
Location ID: 311282



Pic 9 Weeds along fence



Pic 10 Unused equipment.