



LEASE INSPECTION FORM

Date 3/20/85
Operator ROCKY MTH. PROD. Field AMBUSH
Lease Name & No. UPRR-BOX ELDER FMS #12-13 County ADAMS
Tank Battery No. 55-63-E1 INCORRECT Location SW NE 13-25-65W
Legal Description
Type of Inspection PIT / well site
Water Inflow _____ (Bbls. per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)
Type of Tank

SKIM TANK 2 - 300 BBL OIL TANKS
PIT NO. 1 10' DIA. 5' high. FIBER GLASS TANK, OPEN, C/W H₂O
PIT NO. 2 10' X 10' X 10', OPEN, UNLINED, DRY
PIT NO. 3 _____

ADDITIONAL PITS _____

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

LAND PLAT SAYS DRILLING, well is on PRODUCTION w/
PUMP SACK + TANKS

VENTING GAS INTO AIR BY EARTHEN PIT

RECOMMENDED ACTION (If Required) CORRECT TANK I.D., SEND FOR

FM 5/10/85

INSPECTOR JSK

COULD BE PUMPING 2000 OIL, ASKED FOR 50 LBS