

Inspection Photos
Location Name: Ikenouye F 29-23
Location ID: 332782



Photo 1: Wellhead



Photo 2: Centralized Tank Battery

Inspection Photos
Location Name: Ikenouye F 29-23
Location ID: 332782



Photo 3: Appears to be stained soil.