

# Inspection Photos

API: 05-071-07414

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/2/2019

## Inspection Photos



**Photo 1.** There is signs of erosion and vehicle rutting along the road that travels up to the location.



## Inspection Photos



**Photo 2.** It does not appear that risers are LOTO and unused equipment still remains.

## Inspection Photos



**Photo 3.** Facing toward the pit.