

Well Name : Hi-Land 10B

API # : 001-08767



Photo 1: Wellhead sign.



Photo 2: Production equipment building with separator heater stacks visible.

Well Name : Hi-Land 10B
API # : 001-08767



Photo 3: Produced water tank.



Photo 4: (2) production tanks.

Well Name : Hi-Land 10B

API # : 001-08767



Photo 5: Production equipment building with siding and underlayment removed. The roof was in the process of being removed.



Photo 6: Pulling the W horizontal separator out of building.

Well Name : Hi-Land 10B

API # : 001-08767



Photo 7: Fluid released from separator when valve broke off vessel.



Photo 8: Additional view of release.

Well Name : Hi-Land 10B

API # : 001-08767



Photo 9: Horizontal separator removed from building.



Photo 10: Removing impacted soil from release.

Well Name : Hi-Land 10B

API # : 001-08767



Photo 11: (1) of (2) open flow line/risers located inside building.



Photo 12: (2) of (2) open flow lines/risers located inside building.

Well Name : Hi-Land 10B

API # : 001-08767



Photo 13: Cleaned up and secure for the evening.



Photo 14: Additional view of production equipment building.