

Inspection Photos  
Location Name: NGL C2C  
Location ID: 444710



**Photo 1 Wh sign and unused equipment fiberglass pipe**



**Photo 2 Braden head pressure 150psi. Casing pressure 4psi.**

Inspection Photos  
Location Name: NGL C2C  
Location ID: 444710



Colorado Oil and Gas Conservation Commission  
40.01623, -104.89653, 1513.8m  
Apr 3, 2019 10:08:26



Colorado Oil and Gas Conservation Commission  
40.01623, -104.89651, 1512.3m  
Apr 3, 2019 10:09:28

Photo 3 tubing pressure 1806psi

Photo 4 WH photo