

Inspection Photos
Location Name: NGL C2B
Location ID: 443339



Photo 1 WH sign and building



Photo 2 WH

Inspection Photos
Location Name: NGL C2B
Location ID: 443339



Photo 3 silt fence not maintained around perimeter of location



Photo 4 silt fence not maintained around perimeter of location

Inspection Photos
Location Name: NGL C2B
Location ID: 443339



Photo 5 silt fence not maintained around perimeter of location



Photo 6 silt fence not maintained around perimeter of location

Inspection Photos
Location Name: NGL C2B
Location ID: 443339



Photo 7 silt fence not maintained around perimeter of location



Photo 8 silt fence not maintained around perimeter of location