

Inspection Photos
Location Name: NGL UIC Disposal C2C
Facility #:159991



Photo 1 Facility sign

Photo 2 loc pic

Inspection Photos
Location Name: NGL UIC Disposal C2C
Facility #:159991



Photo 3 Trash Cement block near drainage

Photo 4 Unused equipment on north edge of facility

Inspection Photos
Location Name: NGL UIC Disposal C2C
Facility #:159991



Photo 5 Trash: empty spool

Photo 6 Trash: old fencing wooden posts and tee posts

Inspection Photos
Location Name: NGL UIC Disposal C2C
Facility #:159991



Colorado Oil and Gas Conservation Commission
40.02274, -104.88734, 1509.8m
Apr 3, 2019 11:56:39



Colorado Oil and Gas Conservation Commission
40.02244, -104.88799, 1504.8m
Apr 3, 2019 12:01:45

Photo 7 TNK BTRY

Photo 8 office building

Inspection Photos
Location Name: NGL UIC Disposal C2C
Facility #:159991



Colorado Oil and Gas Conservation Commission
40.02285, -104.88813, 1506.7m
Apr 3, 2019 12:35:44



Colorado Oil and Gas Conservation Commission
40.02285, -104.88816, 1507.5m
Apr 3, 2019 12:35:55

Photo 9 Injection pump building

Photo office building

Inspection Photos
Location Name: NGL UIC Disposal C2C
Facility #:159991



Colorado Oil and Gas Conservation Commission
40.02376, -104.88669, 1502.8m
Apr 3, 2019 12:32:06



Colorado Oil and Gas Conservation Commission
40.02383, -104.88615, 1511.1m
Apr 3, 2019 12:32:46

Photo 11 tracking pad

Photo 12 County road 19

Inspection Photos
Location Name: NGL UIC Disposal C2C
Facility #:159991



Photo 13 Drainage ditched rip rapped and sediment trap

Photo 14 cement pan drainage from facility